

Store Conditions of the Assembly

- **If possible,the storing temperature range is within 0~35°C , During storing,temperature should not exceed 50°C.**
- **The storing areas can not place equipment which can produce ozone.For example,mercury vapour lamp 、 high-voltage electric device and other equipment which can produce spark or set out electricity.**
- **The swaged hose assemblies can not be placed with erosive products or exposed over gasvolatile of these product.Far away from heat source and equipment which can produce electric filed or magnetic filed.**
- **Avoid sunshine or strong artificial light source.**
- **Avoid to touch the objects or the ground.**
- **Can not be piled up too high.**
- **Guarantee against rodent attacking.**
- **Observe the rule of “first in,then first out”.**